Origin and Cause Report

2 Ackerman Avenue, Clifton, NJ Client – Crawford & Company, General Adjuster



Engineering inspection and technical report for Crawford & Company, General Adjusters, to determine origin and cause of the electrical power distribution equipment failure after the hurricane "Irene". The inspection and subsequent "Origin and Cause Report" were performed for the following equipment:

- Thermal Fluid Heater
- Power Transformers (4)
- Pulverizer Control Panels (4)
- Thermal Shock Machine
- > Forklift
- Test Press
- Foam Making Machine
- Battery Charger
- Incinerator
- Portable Scales (4)
- Vacuum Pump
- Compressor
- Air Dryer
- Extruder

- ➤ Table Saw

- Stationary Floor Scale
 Forklift Drum Lifter
 UNO Sanding Machine
- Gas Oven
 Timesaver Sanding Machine